



Pro-LIFT G3E

Built from the Ground Up!

Step 9 - Refer to operating instructions
(Provided on a separate sheet)

Step 8 - Attach projector boom
(As per manufacturers specification)

- Attach projector boom onto mounting plate.

Step 7 - Secure Digital Board to Frame
(As per manufacturer specification)

- Position fixing bars so that the holes on the pen tray of the board correspond with holes on the fixing bars.
- Use 4-M6x14mm bolts to attach fixing bars to lifting column.
- Use 2x10-24 bolts & nuts to secure digital board to fixing bars.

Step 6 - Attach digital board
(As per manufacturers specification)

- Use 4x10-24 bolts & nuts provided to secure board brackets to top angle.
- 2 levels of fixing holes provided for large and small boards.

Step 5 - Plug in power cable into power bar
(Press switch to on position)

Step 4 - Attach Top Safety Switch
(Ensure Antenna whip points upward)

- Use 2 bolts provided on safety switch to secure to mounting plate.
- Plug cable to SLS Jack located on Lift Mechanism. Failure to do so will disable unit.

Step 3 - Install Turret Head
(Ensure plate is facing forward as per diagram)

- using 8 wing nuts provided, attach turret head onto top angle.

Step 2 - Install A-Frame Assembly
(Ensure that angle faces forward & casters locked)

- Attach and secure 1 side of A-Frame
- Pull frame to seat over second side.
- Attach & secure using 8 wing nuts provided

Step 1 - Install casters
(Requires 4 bolts - M6 x 14mm per caster)

- Carefully place lift mechanism onto name plate to expose bottom of frame and facilitate fixing of casters.
- When finished, lock all casters and return mechanism to upright position.

OPEN BOX and Identify All parts.



PROPRIETARY AND CONFIDENTIAL
THE INFORMATION CONTAINED IN THIS
DRAWING IS THE SOLE PROPERTY OF
JORO MANUFACTURING CO. LTD. ANY
REPRODUCTION IN PART OR AS A WHOLE
WITHOUT THE WRITTEN PERMISSION OF
JORO MANUFACTURING CO. LTD. IS
PROHIBITED.

JORO Manufacturing Company Ltd.

Pro-LIFT G3E
Assembly Sequence

SIZE A	DWG. NO. JMC-20091117-ProliftG3E-assembly sheet	REV. 0.001
SCALE:1:12	WEIGHT:	SHEET 1 OF 1